

Thanks, jamal

=

=====

>>> "Stan Helenschmidt" <stan.hgi@sbcglobal.net> 9/28/2007 12:09 PM

>>>

Attached is our proposal for the subsurface investigation and design.

I

still need to send you the subcontractor commitment letters and George Meulmester's resume (Appendix A - 4 of 4)

Stan Helenschmidt

Helenschmidt Geotechnical, Inc.

5245 Avenida Encinas, Suite B

Carlsbad, CA 92008

tel 760 579-0333

fax 760 579-0230

From: Rob Hawk
To: HRuhi@sandiego.gov,AOskoui@sandiego.gov,DJarrell@sandiego.gov
Date: September 30, 2007 10:38:32 PM
Subject: Re: Fire Hydrant Leak on Desert View

Afshin/Hossein:

I visited Desert View Alley last night at approximately 8:30 and met the Utilities crew. Reportedly, several neighbors have called about this hydrant leaking throughout the weekend. Joyce Clark, from 5748 Desert View (alley) where the hydrant is located, told me she had called the hotline several times. The leak was coming out of the valve stem area of the water line in the alley, not the hydrant. The neighbors reported that a crew would show up, turn off the valve in the alley, and leave, but the leak continued. The entire hydrant and water line crossing in the alley, and other paved and unpaved areas are showing significant additional distress - mostly heave - when compared to the conditions on Friday afternoon, as is the pavement in several other locations in the alley.

I met the crew there last night; it was this crews first visit to the site. Steve Palmer (1931) and Paul Reynolds (1941) grasped the situation quickly and found a valve in the Desert View Drive street that shut down the line in the alley. They verified that the line was off and left about 9:30.

Cursey examination of Soledad Mountain Road revealed that several old cracks have widened since Friday, and new cracks have appeared since we sealed the existing cracks two weeks ago, so movement is ongoing. New survey data should be available Tuesday afternoon but we need at least one or two additional data sets to confirm whether or not the movement rate is increasing or decreasing.

Robert N. Hawk, PE
Senior Engineering Geologist/Deputy City Engineer
City of San Diego, Engineering and Capital Projects
Field Engineering Division, MS 18
9485 Aero Drive San Diego, CA 92123
(858) 573-5011
(858) 627-3297 (Fax)
rhawk@sandiego.gov

Working Together to Engineer a Better Tomorrow

>>> <tac@san.rr.com> 09/30/07 1:03 PM >>>

Rob,

The fire hydrant on Desert View at 5734 Desert View is flowing water from under the concrete at the base of the hydrant. The neighbors reported it leaking yesterday and it has gotten much worse today. It is seeping into the cracks in the street and into yards. We reported it to the emergency services number today and thought that you should be notified.

Tom

CC:

CDrummond@sandiego.gov,JBatta@sandiego.gov,MGibson@sandiego.gov,DZoumaras@sandiego.gov,SMedina@sandiego.gov,JFisher@sandiego.gov

From: Rob Hawk
To: tac@san.rr.com
Date: Sun, Sep 30, 2007 7:51 PM
Subject: Re: Fwd: Re: Soledad Mountain Road water line/letter to customers

Tom: Do you know if it is still leaking? Do you have the telephone numbers for the neighbors? Has the utility responded yet? Rob Hawk

Robert N. Hawk, PE
Senior Engineering Geologist/Deputy City Engineer
City of San Diego, Engineering and Capital Projects
Field Engineering Division, MS 18
9485 Aero Drive San Diego, CA 92123
(858) 573-5011
(858) 627-3297 (Fax)
rhawk@sandiego.gov

Working Together to Engineer a Better Tomorrow

>>> <tac@san.rr.com> 09/30/07 4:47 PM >>>
Rob,

The hydrant is still leaking it is soaking the ground please have it turned off as soon as possible. One night of leaking at this rate the hill will be gone.

Help tom

----- Original Message -----

From: Rob Hawk <rhawk@sandiego.gov>
Date: Wednesday, September 26, 2007 9:20 pm
Subject: Re: Fwd: Re: Soledad Mountain Road water line/letter to customers
To: tac@san.rr.com
Cc: Jamal Batta <JBatta@sandiego.gov>

> Thanks Tom, but it was Jamal (Batta) who got the speedy response and
> deserves the credit.

>

> Rob Hawk

>

> Robert N. Hawk, PE
> Senior Engineering Geologist/Deputy City Engineer
> City of San Diego, Engineering and Capital Projects
> Field Engineering Division, MS 18
> 9485 Aero Drive San Diego, CA 92123
> (858) 573-5011
> (858) 627-3297 (Fax)
> rhawk@sandiego.gov

>

> Working Together to Engineer a Better Tomorrow

>

> >>> <tac@san.rr.com> 09/26/07 7:19 PM >>>

> Rob,

>

> I met Mr. Batta last night while he was here. We had a small flood

> in
> the water meter box at 5695 soledad mtn rd. The water people did
> not
> hook it up right. They did show up later to fix it. The two large
> patches on the street where the water main breaks happened need to
> be
> smoothed out when cars and trucks hit them it makes a loud noise
> and
> vibration in ours and our neighbors house. They fixed the patch by
> the
> curb today thank you for taking care of that.

>
> Tom Crabbe
>
>
>

> ----- Original Message -----

> From: Rob Hawk <rhawk@sandiego.gov>
> Date: Tuesday, September 25, 2007 5:37 pm
> Subject: Re: Fwd: Re: Soledad Mountain Road water line/letter to
> customers
> To: tac@san.rr.com
> Cc: Jamal Batta <JBatta@sandiego.gov>, Michael Handal
> <MHandal@sandiego.gov>

>
> > Thanks Tom; I will pass it along to the project manager. Rob Hawk
> >

> > Robert N. Hawk, PE
> > Senior Engineering Geologist/Deputy City Engineer
> > City of San Diego, Engineering and Capital Projects
> > Field Engineering Division, MS 18
> > 9485 Aero Drive San Diego, CA 92123
> > (858) 573-5011
> > (858) 627-3297 (Fax)
> > rhawk@sandiego.gov

> >
> > Working Together to Engineer a Better Tomorrow
> >

> > > > <tac@san.rr.com> 09/25/07 4:20 PM >>>

> > Mr. Hawk,

> >
> > The large trucks traveling by are causing large sink holes in
> the

> > new
> > repair areas these are in front of 5695 soledad mtn rd. large
> > amounts

> > of water from the gutter is seeping into the street. can it
> please

> > be
> > repaired to keep any further damage to the street and
> surrounding
> > areas. this large hole is over the gas line repair.

> >
> > Thank You Tom Crabbe

> >
> > ----- Original Message -----

> > From: Rob Hawk <RHawk@sandiego.gov>
> > Date: Thursday, September 20, 2007 9:30 am
> > Subject: Re: Fwd: Re: Soledad Mountain Road water line/letter to
> > customers
> > To: tac@san.rr.com
> >
> > > Mr. Crabbe: Contractors should be on your road today working
> > on
> > > sealingthe pavement. Road Works Inc., the crack sealers,
> > should
> > > be at the site
> > > now. Be sure to call the hotline number; Carol can probably
> > get
> > > back to
> > > you faster than I can.
> > >
> > > Rob Hawk
> > >
> > > > <tac@san.rr.com> 9/20/07 6:49:42 AM >>>
> > > The large gaps in the road and along the curb on the even side
> > > of
> > > the
> > > road need to be sealed. It rained last night and will rain
> > > more
> > > next
> > > two days. There's another gas leak in front of 5695 soledad
> > > mtn
> > > rd. I
> > > called gas company last night they are to come out today.
> > >
> > > ----- Original Message -----
> > > From: Rob Hawk <RHawk@sandiego.gov>
> > > Date: Wednesday, September 19, 2007 3:49 pm
> > > Subject: Fwd: Re: Soledad Mountain Road water line/letter to
> > > customers
> > > To: yluza@aol.com, tac@san.rr.com
> > >
> > > > You should be finding a letter like the attached delivered
> > > to
> > > > you
> > > > todayor tomorrow. As it says, we will be doing some work up
> > > there
> > > to
> > > > determine the cause of the leaks. Rob Hawk
> > > >
> > > > Robert N. Hawk, PE
> > > > Senior Engineering Geologist/Deputy City Engineer
> > > > City of San Diego, Engineering and Capital Projects
> > > > Field Engineering Division, MS 18
> > > > 9485 Aero Drive San Diego, CA 92123
> > > > (858) 573-5011
> > > > (858) 627-3297 (Fax)
> > > > rhawk@sandiego.gov
> > > >
> > > > Working Together to Engineer a Better Tomorrow
> > > >

•
>>>
>>>
>>
>>
>
>
>

CC: JBatta@sandiego.gov,SMedina@sandiego.gov

From: Rob Hawk
To: aoskoui@sandiego.gov; hruhi
Date: September 30, 2007 8:10:03 PM
Subject: Re: Fire Hydrant Leak on Desert View

Afshin, et al: I've spoken with emergency dispatch at 8PM. This leak was called in at least 3 times, but the dispatcher said she notified the crews of the leak. The water supervisor called me at 8:05 and has sent someone out, and is going out himself. He said that a crew had been out earlier today. He did not know what action had been taken.

I am meeting him out there so I will send a report off later tonight. See you in the morning.

Rob Hawk
cell 619-980-7161

Robert N. Hawk, PE
Senior Engineering Geologist/Deputy City Engineer
City of San Diego, Engineering and Capital Projects
Field Engineering Division, MS 18
9485 Aero Drive San Diego, CA 92123
(858) 573-5011
(858) 627-3297 (Fax)
rhawk@sandiego.gov

Working Together to Engineer a Better Tomorrow

>>> <tac@san.rr.com> 09/30/07 1:03 PM >>>
Rob,

The fire hydrant on Desert View at 5734 Desert View is flowing water from under the concrete at the base of the hydrant. The neighbors reported it leaking yesterday and it has gotten much worse today. It is seeping into the cracks in the street and into yards. We reported it to the emergency services number today and thought that you should be notified.

Tom

CC: CDrummond@sandiego.gov, JBatta@sandiego.gov

From: Rob Hawk
To: tac@san.rr.com
Date: 9/30/2007 7:51:15 PM
Subject: Re: Fwd: Re: Soledad Mountain Road water line/letter to customers

Tom: Do you know if it is still leaking? Do you have the telephone numbers for the neighbors? Has the utility responded yet? Rob Hawk

Robert N. Hawk, PE
Senior Engineering Geologist/Deputy City Engineer
City of San Diego, Engineering and Capital Projects
Field Engineering Division, MS 18
9485 Aero Drive San Diego, CA 92123
(858) 573-5011
(858) 627-3297 (Fax)
rhawk@sandiego.gov

Working Together to Engineer a Better Tomorrow

>>> <tac@san.rr.com> 09/30/07 4:47 PM >>>
Rob,

The hydrant is still leaking it is soaking the ground please have it turned off as soon as possible. One night of leaking at this rate the hill will be gone.

Help tom

----- Original Message -----

From: Rob Hawk <rhawk@sandiego.gov>
Date: Wednesday, September 26, 2007 9:20 pm
Subject: Re: Fwd: Re: Soledad Mountain Road water line/letter to customers
To: tac@san.rr.com
Cc: Jamal Batta <JBatta@sandiego.gov>

> Thanks Tom, but it was Jamal (Batta) who got the speedy response and
> deserves the credit.

>

> Rob Hawk

>

> Robert N. Hawk, PE
> Senior Engineering Geologist/Deputy City Engineer
> City of San Diego, Engineering and Capital Projects
> Field Engineering Division, MS 18
> 9485 Aero Drive San Diego, CA 92123
> (858) 573-5011
> (858) 627-3297 (Fax)
> rhawk@sandiego.gov

>

> Working Together to Engineer a Better Tomorrow

>

> >>> <tac@san.rr.com> 09/26/07 7:19 PM >>>

> Rob,

>

> I met Mr. Batta last night while he was here. We had a small flood

> in
> the water meter box at 5695 soledad mtn rd. The water people did
> not
> hook it up right. They did show up later to fix it. The two large
> patches on the street where the water main breaks happened need to
> be
> smoothed out when cars and trucks hit them it makes a loud noise
> and
> vibration in ours and our neighbors house. They fixed the patch by
> the
> curb today thank you for taking care of that.

>
> Tom Crabbe
>
>

> ----- Original Message -----

> From: Rob Hawk <rhawk@sandiego.gov>
> Date: Tuesday, September 25, 2007 5:37 pm
> Subject: Re: Fwd: Re: Soledad Mountain Road water line/letter to
> customers
> To: tac@san.rr.com
> Cc: Jamal Batta <JBatta@sandiego.gov>, Michael Handal
> <MHandal@sandiego.gov>
>

> > Thanks Tom; I will pass it along to the project manager. Rob Hawk
> >

> > Robert N. Hawk, PE
> > Senior Engineering Geologist/Deputy City Engineer
> > City of San Diego, Engineering and Capital Projects
> > Field Engineering Division, MS 18
> > 9485 Aero Drive San Diego, CA 92123
> > (858) 573-5011
> > (858) 627-3297 (Fax)
> > rhawk@sandiego.gov
> >

> > Working Together to Engineer a Better Tomorrow
> >

> > > > <tac@san.rr.com> 09/25/07 4:20 PM > > >

> > Mr. Hawk,
> >

> > The large trucks traveling by are causing large sink holes in
> the

> > new
> > repair areas these are in front of 5695 soledad mtn rd. large
> > amounts

> > of water from the gutter is seeping into the street. can it
> please

> > be
> > repaired to keep any further damage to the street and
> surrounding
> > areas. this large hole is over the gas line repair.

> >
> > Thank You Tom Crabbe
> >

> > ----- Original Message -----

> > From: Rob Hawk <RHawk@sandiego.gov>
> > Date: Thursday, September 20, 2007 9:30 am
> > Subject: Re: Fwd: Re: Soledad Mountain Road water line/letter to
> > customers
> > To: tac@san.rr.com
> >
> > > Mr. Crabbe: Contractors should be on your road today working
> > on
> > > sealingthe pavement. Road Works Inc., the crack sealers,
> > should
> > > be at the site
> > > now. Be sure to call the hotline number; Carol can probably
> > get
> > > back to
> > > you faster than I can.
> > >
> > > Rob Hawk
> > >
> > > > <tac@san.rr.com> 9/20/07 6:49:42 AM >>>
> > > The large gaps in the road and along the curb on the even side
> > of
> > > the
> > > road need to be sealed. It rained last night and will rain
> > more
> > > next
> > > two days. There's another gas leak in front of 5695 soledad
> > mtn
> > > rd. I
> > > called gas company last night they are to come out today.
> > >
> > > ----- Original Message -----
> > > From: Rob Hawk <RHawk@sandiego.gov>
> > > Date: Wednesday, September 19, 2007 3:49 pm
> > > Subject: Fwd: Re: Soledad Mountain Road water line/letter to
> > > customers
> > > To: yluza@aol.com, tac@san.rr.com
> > >
> > > > You should be finding a letter like the attached delivered
> > > to
> > > > you
> > > > todayor tomorrow. As it says, we will be doing some work up
> > > there
> > > > to
> > > > determine the cause of the leaks. Rob Hawk
> > > >
> > > > Robert N. Hawk, PE
> > > > Senior Engineering Geologist/Deputy City Engineer
> > > > City of San Diego, Engineering and Capital Projects
> > > > Field Engineering Division, MS 18
> > > > 9485 Aero Drive San Diego, CA 92123
> > > > (858) 573-5011
> > > > (858) 627-3297 (Fax)
> > > > rhawk@sandiego.gov
> > > >
> > > > Working Together to Engineer a Better Tomorrow
> > > >

> > >
> > >
> >
> >
>
>
>

CC: JBatta@sandiego.gov,SMedina@sandiego.gov

100

From: Rob Hawk
To: Bertch, Tim; Bradford, Jaymie; Brown, John; Conf 600B 8 8A; Fisher, Jim; Haas, Richard; Hawk, Rob; Jarrell, David; Mercer, Mark; Oskoui, Afshin; Palmucci, Ray; Ruhi, Hossein; Ruiz, Alex; Sierra, Mario; Toth, Christopher; Yee, Peter; Yousef, Hasan; Zeleny, Thomas
Date: Monday, October 01, 2007
Time: 8:00:00 AM - 8:30:00 AM
Subject: Soledad Mountain Road
Place: Conf 600B 8 8A

I apologize in advance for the 8AM Monday meeting. With this large a group, it is difficult to include everyone. If you can't make it, please send a surrogate.

Rob Hawk

Robert N. Hawk, PE
Senior Engineering Geologist/Deputy City Engineer
City of San Diego, Engineering and Capital Projects
Field Engineering Division, MS 18
9485 Aero Drive San Diego, CA 92123
(858) 573-5011
(858) 627-3297 (Fax)
rhawk@sandiego.gov

Working Together to Engineer a Better Tomorrow

CC: Batta, Jamal; Gibson, Marnell; Zoumaras, Dave

From: Jamal Batta
To: Jamal Batta
Date: 10/1/2007
Time: 1:00:00 PM - 2:00:00 PM
Subject: Soledad Mountain Road
Place: Mayor's office

From: Kevin Gensler
To: Salvador Rodriguez
Date: 10/1/2007 10:47:01 AM
Subject: Soledad Mtn. Rd.

Sal,
Per. Chris, we need to televise the following FSNs ✓

8323 ✓

8322 ✓

8316 ✓

8312 ✓

8311 ✓

5185137 ✓

We need to televise the following FSNs once a week until further notice,

8308

8306

8307

8330

Kevin

CC: Melody Shaw-Sydnor; Mike Bedard

0 0 0 0 0

PRG/KY

From: Jamal Batta
To: Stan Medina
Date: 10/1/2007 10:46:00 AM
Subject: Fwd: Re: Fire Hydrant Leak on Desert View

FYI_ This is regarding the FH down below in the alley.

=====

>>> <tac@san.rr.com> 10/1/2007 9:25 AM >>>
MR. Batta,

It is still leaking

----- Original Message -----

From: Jamal Batta <jbatta@san.rr.com>
Date: Monday, October 1, 2007 7:34 am
Subject: Re: Fire Hydrant Leak on Desert View
To: tac@san.rr.com

> Tom:
>
> I reported it my self also to the hotline on Friday afternoon. Is it
> fixed or not yet?
>
> Please let me know if you happened to know.
>
>
> Respectfully,
>
> Jamal Batta, PE, CFM
> Senior Civil Engineer
> Engineering and Capital Projects
> City of San Diego
> Phone: 619 533-3769
> Fax: 619 533-3071
> MS # 612
> JBATTA@SANDIEGO.GOV
>

CC: Afshin Oskoui; Jim Fisher; Rob Hawk

From: Richard Haas
To: Afshin Oskoui; David Jarrell; Greg Bych; Jamal Batta; Ray Palmucci; Rob Hawk; Thomas Zeleny
Date: Mon, Oct 1, 2007 11:09 AM
Subject: Fwd: Brief/La Jolla

Please forward to the Risk Management rep who was at our 10:00 meeting. I didn't get his name.

Please rearrange your schedules to attend.

Thanks,

Rich

From: Rob Hawk
To: Batta, Jamal; Handal, Michael; Hopkins, John
Date: Mon, Oct 1, 2007 3:35 PM
Subject: Re: Soledad Mtn Road landslide

Yeah; I'd like to know that too. Rob

>>> John Hopkins 10/1/07 7:01:32 AM >>>
Good Morning,

Can you please tell me the Job Order (WO) you are using for the Soledad Mtn Road landslide job?

Thanks

John Hopkins
Field Division Analyst
[858] 627-3204
[858] 627-3297 (Fax)

From: Jamal Batta
To: Rob Hawk; Ventimiglia_Tim@emc.com
Date: 10/1/2007 3:36:49 PM
Subject: Re: Soledad Mountain Road Landslide

Mr. Ventimiglia:

Thank you for sharing this information with us. I and Rob Hawk will be on site this afternoon at 4:00p.m. to visit with every homeowner between 5685 to 5735 Soledad Mtn Rd, to share with them what we know.

Respectfully,

Jamal Batta, PE, CFM
Senior Civil Engineer
Engineering and Capital Projects
City of San Diego
Phone: 619 533-3769
Fax: 619 533-3071
MS # 612
JBATTA@SANDIEGO.GOV

>>> <Ventimiglia_Tim@emc.com> 10/1/2007 1:10 PM >>>

Robert and Jamal,

My name is Tim Ventimiglia. My wife, Chere, and I live at 5785 Soledad Mountain Road. I am emailing you due to the tremendous concern I have for the issues that are occurring on my street.

My neighbor at 5703 Soledad Mountain Road, Mr. Tom Crabbe, has filled me in on the details of the water leaks, possible sewer leak(s), and landslide that is occurring down our street. I've talked with one of the San Diego Gas & Electric employees today regarding the land movement, and he told me that the land has moved feet, not just inches! I see the damage to the street and the homes down my street, the damage to the street below us (Desert View), and I see that there are many city employees working on these issues. However, I still am very concerned for my property, and I wonder if I should be concerned for my life. The ground around my home is saturated with water. See attached pictures. This hole that I dug is approximately 2 feet deep, and shows how saturated the clay is. Even though this water, I assume, could be caused by the leaks down our street - approximately 1/2 block down - our house is also higher in altitude. This makes me wonder if there are other leaks. I would like for you to come by our home and take a look at this and provide an assessment of this information.

Also, my wife and I have smelled a strong odor of sewer gas (wind was from the Northwest, not from the South where the city crews are working) many times within the last two weeks, and we wonder if there is a sewer leak North of where the city crews are working.

Last, I would like to be kept informed of what problems are found, and what measures are being implemented to address these problems. Hearing about these issues from my neighbor, I feel, is inadequate. I look forward to your response, and your visit.

Tim Ventimiglia

<<CIMG1085.JPG>> <<CIMG1084.JPG>>

CC: "AfshinOskoui@sandiego.gov".GWIA3.Yosemite@sandiego.gov;
"AlexRuiz@sandiego.gov".GWIA3.Yosemite@sandiego.gov;
"ChristopherToth@sandiego.gov".GWIA3.Yosemite@sandiego.gov;
"MarioSierra@sandiego.gov".GWIA3.Yosemite@sandiego.gov;
"RichHaas@sandiego.gov".GWIA3.Yosemite@sandiego.gov; chere@san.rr.com; Council Member Kevin
Faulconer; Scott Peters Public

From: Jamal Batta
To: Duncan Hughes
Date: 10/1/2007 11:14:15 AM
Subject: Soledad Mountain Road - Traffic Speed

Duncan:

I am getting lots of heat on this. We need to put signs to lower the speed to 25 mph and also to detour trucks from using the road. Hasan knows the urgency in case you need his help to move things fast over in the sign shop.

Another issue came up this morning regarding the bike lane as to its safety. I'll go to the site to see the width of the cracks in the bike lane so we may close it. For now, we need signs to caution people to slow in the bike lane.

The most critical area is between 5735 to 5685 Soledad Mountain Road.

Thanks, jamal

CC: Deborah Van Wanseele; Hasan Yousef

From: Jamal Batta
To: Duncan Hughes
Date: 10/1/2007 11:51:30 AM
Subject: Re: Soledad Mountain Road - Traffic Speed

Do yo evaluate bike lanes or you want me to do it. Please let me know.

Thanks, jamal

=

=====

>>> Duncan Hughes 10/1/2007 11:24 AM >>>

We have issued work orders to Street Division for the installation of advisory speed signage and a truck prohibition and detour. Please be aware that the speed will not be enforceable, and neither will the truck prohibition. There is no way to sign for reduced speed in the bike lane. If there is a dangerous condition the bike lane should be closed.

Hasan can let you know when the signs will be installed.

Duncan

>>> Jamal Batta 10/01/07 11:14 AM >>>

Duncan:

I am getting lots of heat on this. We need to put signs to lower the speed to 25 mph and also to detour trucks from using the road. Hasan knows the urgency in case you need his help to move things fast over in the sign shop.

Another issue came up this morning regarding the bike lane as to its safety. I'll go to the site to see the width of the cracks in the bike lane so we may close it. For now, we need signs to caution people to slow in the bike lane.

The most critical area is between 5735 to 5685 Soledad Mountain Road.

Thanks, jamal

CC: Deborah Van Wanseele; Deena Smith; Gary Pence; Hasan Yousef

From: Thyme Curtis
To: Jamal Batta
Date: Mon, Oct 1, 2007 3:38 PM
Subject: Fwd: Soledad MTn Rd leaks

Hi Jamal,

It was nice meeting today, thanks for your help on this issue.

Could you contact the gentleman below regarding the situation on Soledad Mtn Road? He was very concerned last week and I left him a voice message today saying that you would be calling him to explain the situation. I do not know if he is one of the houses that is immediately affected.

Thank you, and I will speak with you soon!

Thyme

Thyme Curtis
Council Representative
Councilmember Kevin Faulconer, Second District
(619) 236-7351 (phone)
(619) 236-6996 (fax)

Disclosure: This email is public information. Correspondence to and from this email address is recorded and may be viewed by third parties and the public upon request.

>>> Thyme Curtis 9/28/2007 10:32 AM >>>

Victor Lahvichek would like to be updated with the drainage issues. 858.459.6591

Thyme Curtis
Council Representative
Councilmember Kevin Faulconer, Second District
(619) 236-7351 (phone)
(619) 236-6996 (fax)

Disclosure: This email is public information. Correspondence to and from this email address is recorded and may be viewed by third parties and the public upon request.

From: Thyme Curtis
To: Jamal Batta; rhawk@sandiego.gov
Date: Mon, Oct 1, 2007 3:45 PM
Subject: Fwd: Soledad Mountain Road Landslide

Hi Robert and Jamal,

This is the only email I've received about saturated land, though this email is of great concern to me as the person lives at the top of the land movement. Can you keep me posted as to why you believe his land is wet?

I believe the other people that have mentioned saturated land were at the bottom on Desert View.

Thanks for your help,
thyme

Thyme Curtis
Council Representative
Councilmember Kevin Faulconer, Second District
(619) 236-7351 (phone)
(619) 236-6996 (fax)

Disclosure: This email is public information. Correspondence to and from this email address is recorded and may be viewed by third parties and the public upon request.

>>> <Ventimiglia_Tim@emc.com> 10/1/2007 1:10 PM >>>

Robert and Jamal,

My name is Tim Ventimiglia. My wife, Chere, and I live at 5785 Soledad Mountain Road. I am emailing you due to the tremendous concern I have for the issues that are occurring on my street.

My neighbor at 5703 Soledad Mountain Road, Mr. Tom Crabbe, has filled me in on the details of the water leaks, possible sewer leak(s), and landslide that is occurring down our street. I've talked with one of the San Diego Gas & Electric employees today regarding the land movement, and he told me that the land has moved feet, not just inches! I see the damage to the street and the homes down my street, the damage to the street below us (Desert View), and I see that there are many city employees working on these issue. However, I still am very concerned for my property, and I wonder if I should be concerned for my life.

The ground around my home is saturated with water. See attached pictures. This hole that I dug is approximately 2 feet deep, and shows how saturated the clay is. Even though this water, I assume, could be caused by the leaks down our street - approximately 1/2 block down - our house is also higher in altitude. This makes me wonder if there are other leaks. I would like for you to come by our home and take a look at this and provide an assessment of this information.

Also, my wife and I have smelled a strong odor of sewer gas (wind was from the Northwest, not from the South where the city crews are working) many times within the last two weeks, and we wonder if there is a sewer leak North of where the city crews are working.

Last, I would like to be kept informed of what problems are found, and what measures are being implemented to address these problems. Hearing about these issues from my neighbor, I feel, is inadequate.

I look forward to your response, and your visit.

From: Jamal Batta
To: Afshin Oskoui; Alex Ruiz; Christopher Toth; Mario Sierra; Richard Haas
Date: 10/1/2007 3:47:08 PM
Subject: Fwd: Re: Soledad Mountain Road Landslide

You were cc'd on the attached e mail by Mr. Ventimiglia . I've already responded to him. Just to let you know in case you didn't receive a copy.....jamal,

CC: "AfshinOskoui@sandiego.gov".GWIA3.Yosemite@sandiego.gov;
"AlexRuiz@sandiego.gov".GWIA3.Yosemite@sandiego.gov;
"ChristopherToth@sandiego.gov".GWIA3.Yosemite@sandiego.gov;
"MarioSierra@sandiego.gov".GWIA3.Yosemite@sandiego.gov;
"RichHaas@sandiego.gov".GWIA3.Yosemite@sandiego.gov; chere@san.r.rr.com; Council Member
Kevin Faulconer; Scott Peters Public

From: Jamal Batta
To: Rob Hawk; Ventimiglia_Tim@emc.com
Date: 10/1/2007 3:36:49 PM
Subject: Re: Soledad Mountain Road Landslide

Mr. Ventimiglia:

Thank you for sharing this information with us. I and Rob Hawk will be on site this afternoon at 4:00p.m. to visit with every homeowner between 5685 to 5735 Soledad Mtn Rd, to share with them what we know.

Respectfully,

Jamal Batta, PE, CFM
Senior Civil Engineer
Engineering and Capital Projects
City of San Diego
Phone: 619 533-3769
Fax: 619 533-3071
MS # 612
JBATTA@SANDIEGO.GOV

>>> <Ventimiglia_Tim@emc.com> 10/1/2007 1:10 PM >>>

Robert and Jamal,

My name is Tim Ventimiglia. My wife, Chere, and I live at 5785 Soledad Mountain Road. I am emailing you due to the tremendous concern I have for the issues that are occurring on my street.

My neighbor at 5703 Soledad Mountain Road, Mr. Tom Crabbe, has filled me in on the details of the water leaks, possible sewer leak(s), and landslide that is occurring down our street. I've talked with one of the San Diego Gas & Electric employees today regarding the land movement, and he told me that the land has moved feet, not just inches! I see the damage to the street and the homes down my street, the damage to the street below us (Desert View), and I see that there are many city employees working on these issue. However, I still am very concerned for my property, and I wonder if I should be concerned for my life. The ground around my home is saturated with water. See attached pictures. This hole that I dug is approximately 2 feet deep, and shows how saturated the clay is. Even though this water, I assume, could be caused by the leaks down our street - approximately 1/2 block down - our house is also higher in altitude. This makes me wonder if there are other leaks. I would like for you to come by our home and take a look at this and provide an assessment of this information.

Also, my wife and I have smelled a strong odor of sewer gas (wind was from the Northwest, not from the South where the city crews are working) many times within the last two weeks, and we wonder if there is a sewer leak North of where the city crews are working.

Last, I would like to be kept informed of what problems are found, and what measures are being implemented to address these problems. Hearing about these issues from my neighbor, I feel, is inadequate.

I look forward to your response, and your visit.

Tim Ventimiglia

<<CIMG1085.JPG>> <<CIMG1084.JPG>>

From: Rob Hawk
To: SMedina@sandiego.gov
Date: Mon, Oct 1, 2007 8:54 PM
Subject: Re: Soledad Mt. Rd.

You should be safe to place the hydrant north of the Clark residence at 5748; so any address higher than that one. However, I cannot tell whether or not the line coming up from Desert View Street is going to be affected if part of it is still in the alley near 5748. The toe may cross the entire width of the alley at that location. Can we get a letter of permission to cross the property at the north end, and bring up a temporary line? The existing toe may also extend eastward as the slide develops. Rob

Robert N. Hawk, PE
Senior Engineering Geologist/Deputy City Engineer
City of San Diego, Engineering and Capital Projects
Field Engineering Division, MS 18
9485 Aero Drive San Diego, CA 92123
(858) 573-5011
(858) 627-3297 (Fax)
rhawk@sandiego.gov

Working Together to Engineer a Better Tomorrow

>>> Stan Medina 10/01/07 4:54 PM >>>

Hello Rob,

Regarding the fire hydrant located in the alley between Soledad Mt. Rd. & Desert View:

Would you know the exact location of the toe of the slide? We are strategizing options to relocate the fire hydrant. Our first option would be to turn the lateral north, on the furthest easterly side of the alley and install one out of the slide area.

Our concern is if it's out of the toe of the slide area?

Thanks

Stan Medina
Construction Program Manager
Water Department, Operations
619-527-7434

CC: JFisher@sandiego.gov,JBatta@sandiego.gov,MHandal@sandiego.gov

Jim Fisher - Fwd: Re: Soledad Mountain Road Landslide

From: Alex Ruiz
To: Jim Fisher; Stan Griffith
Date: 10/1/2007 4:58 PM
Subject: Fwd: Re: Soledad Mountain Road Landslide

The attached e-mail is another report from a concerned resident. He has concerns about the "saturated" soil near his home and the "sewer odor" that he has smelled.... Jamal and Rob Hawk were apparently meeting with the residents today at 4pm and should have an update for tomorrow, but it looks like "more leaks" is a concern... Have we had leak detection in the area to confirm/rule out any more water leaks from pulled services?

Alex

(619) 533-6692
Assistant Director
Water Department

>>> Jamal Batta 10/1/2007 3:47 PM >>>

You were cc'd on the attached e mail by Mr. Ventimiglia . I've already responded to him. Just to let you know in case you didn't receive a copy.....jamal,

From: Jamal Batta
To: Rob Hawk; Ventimiglia_Tim@emc.com
Date: 10/1/2007 3:36:49 PM
Subject: Re: Soledad Mountain Road Landslide

Mr. Ventimiglia:

Thank you for sharing this information with us. I and Rob Hawk will be on site this afternoon at 4:00p.m. to visit with every homeowner between 5685 to 5735 Soledad Mtn Rd, to share with them what we know.

Respectfully,

Jamal Batta, PE, CFM
Senior Civil Engineer
Engineering and Capital Projects
City of San Diego
Phone: 619 533-3769
Fax: 619 533-3071
MS # 612
JBATTA@SANDIEGO.GOV

>>> <Ventimiglia_Tim@emc.com> 10/1/2007 1:10 PM >>>

Robert and Jamal,
My name is Tim Ventimiglia. My wife, Chere, and I live at 5785 Soledad Mountain Road. I am emailing you due to the tremendous concern I have for the issues that are occurring on my street.
My neighbor at 5703 Soledad Mountain Road, Mr. Tom Crabbe, has filled me in on the details of the water leaks, possible sewer leak(s), and landslide that is occurring down our street. I've talked with one of the San Diego Gas & Electric employees today regarding the land movement, and he told me that the land has moved feet, not just inches! I see the damage to the street and the homes down my street, the damage to the street below us (Desert View), and I see that there are many city employees working on these issue. However, I still am very concerned for my property, and I wonder if I should be concerned for my life.
The ground around my home is saturated with water. See attached pictures. This hole that I dug is approximately 2 feet deep, and shows how saturated the clay is. Even though this water, I assume, could be caused by the leaks down our street - approximately 1/2 block down - our house is also higher in altitude. This makes me wonder if there are other leaks. I would like for you to come by our home and take a look at this and provide an assessment of this information.
Also, my wife and I have smelled a strong odor of sewer gas (wind was from the Northwest, not from the South where the city crews are working) many times within the last two weeks, and we wonder if there is a sewer leak North of where the city crews are working.
Last, I would like to be kept informed of what problems are found, and what measures are being implemented to address these problems. Hearing about these issues from my neighbor, I feel, is inadequate.
I look forward to your response, and your visit.
Tim Ventimiglia

<<CIMG1085.JPG>> <<CIMG1084.JPG>>

CC: "AfshinOskoui@sandiego.gov".GWIA3.Yosemite@sandiego.gov;
"AlexRuiz@sandiego.gov".GWIA3.Yosemite@sandiego.gov;
"ChristopherToth@sandiego.gov".GWIA3.Yosemite@sandiego.gov;
"MarioSierra@sandiego.gov".GWIA3.Yosemite@sandiego.gov;
"RichHaas@sandiego.gov".GWIA3.Yosemite@sandiego.gov; chere@san.rr.com; Council Member Kevin
Faulconer; Scott Peters Public

From: Rob Hawk
To: SMedina@sandiego.gov
Date: 10/1/2007 8:54:03 PM
Subject: Re: Soledad Mt. Rd.

You should be safe to place the hydrant north of the Clark residence at 5748; so any address higher than that one. However, I cannot tell whether or not the line coming up from Desert View Street is going to be affected if part of it is still in the alley near 5748. The toe may cross the entire width of the alley at that location. Can we get a letter of permission to cross the property at the north end, and bring up a temporary line? The existing toe may also extend eastward as the slide develops. Rob

Robert N. Hawk, PE
Senior Engineering Geologist/Deputy City Engineer
City of San Diego, Engineering and Capital Projects
Field Engineering Division, MS 18
9485 Aero Drive San Diego, CA 92123
(858) 573-5011
(858) 627-3297 (Fax)
rhawk@sandiego.gov

Working Together to Engineer a Better Tomorrow

>>> Stan Medina 10/01/07 4:54 PM >>>

Hello Rob,

Regarding the fire hydrant located in the alley between Soledad Mt. Rd. & Desert View:

Would you know the exact location of the toe of the slide? We are strategizing options to relocate the fire hydrant. Our first option would be to turn the lateral north, on the furthest easterly side of the alley and install one out of the slide area.

Our concern is if it's out of the toe of the slide area?

Thanks

Stan Medina
Construction Program Manager
Water Department, Operations
619-527-7434

CC: JFisher@sandiego.gov,JBatta@sandiego.gov,MHandal@sandiego.gov

From: Rob Hawk
To: TCurtis@sandiego.gov, JBatta@sandiego.gov
Date: Mon, Oct 1, 2007 9:26 PM
Subject: Re: Fwd: Soledad Mountain Road Landslide

Thyme: this person lives several houses away from the land movement.

I have no idea why is land is wet, but we havn't had reported water leaks that I'm aware of . He may have plumbing leaks on his property, or he may over-irigate. I've offered to meet with him to discuss. Rob Hawk

Robert N. Hawk, PE
Senior Engineering Geologist/Deputy City Engineer
City of San Diego, Engineering and Capital Projects
Field Engineering Division, MS 18
9485 Aero Drive San Diego, CA 92123
(858) 573-5011
(858) 627-3297 (Fax)
rhawk@sandiego.gov

Working Together to Engineer a Better Tomorrow

>>> Thyme Curtis 10/01/07 3:45 PM >>>
Hi Robert and Jamal,

This is the only email I've received about saturated land, though this email is of great concern to me as the person lives at the top of the land movement. Can you keep me posted as to why you believe his land is wet?

I believe the other people that have mentioned saturated land were at the bottom on Desert View.

Thanks for your help,
thyme

Thyme Curtis
Council Representative
Councilmember Kevin Faulconer, Second District
(619) 236-7351 (phone)
(619) 236-6996 (fax)

Disclosure: This email is public information. Correspondence to and from this email address is recorded and may be viewed by third parties and the public upon request.

>>> <Ventimiglia_Tim@emc.com> 10/1/2007 1:10 PM >>>

Robert and Jamal,
My name is Tim Ventimiglia. My wife, Chere, and I live at 5785 Soledad Mountain Road. I am emailing you due to the tremendous concern I have for the issues that are occurring on my street.
My neighbor at 5703 Soledad Mountain Road, Mr. Tom Crabbe, has filled me in on the details of the water leaks, possible sewer leak(s), and landslide that is occurring down our street. I've talked with one of the San Diego Gas & Electric employees today regarding the land movement, and he told me that the land has moved feet, not just inches! I see the damage to the street and the homes down my street, the damage

to the street below us (Desert View), and I see that there are many city employees working on these issue. However, I still am very concerned for my property, and I wonder if I should be concerned for my life.

The ground around my home is saturated with water. See attached pictures. This hole that I dug is approximately 2 feet deep, and shows how saturated the clay is. Even though this water, I assume, could be caused by the leaks down our street - approximately 1/2 block down - our house is also higher in altitude. This makes me wonder if there are other leaks. I would like for you to come by our home and take a look at this and provide an assessment of this information.

Also, my wife and I have smelled a strong odor of sewer gas (wind was from the Northwest, not from the South where the city crews are working) many times within the last two weeks, and we wonder if there is a sewer leak North of where the city crews are working.

Last, I would like to be kept informed of what problems are found, and what measures are being implemented to address these problems. Hearing about these issues from my neighbor, I feel, is inadequate.

I look forward to your response, and your visit.

Tim Ventimiglia

<<CIMG1085.JPG>> <<CIMG1084.JPG>>

From: Rob Hawk
To: MHandal@san Diego.gov, JBatta@san Diego.gov, stan.hgi@sbcglobal.net
Date: Tue, Oct 2, 2007 6:50 AM
Subject: Re: Meeting with contractor at 9:30 am on 10/2/2007, at 5725 SMR

I got tagged by Ron Sainz for a news conference; I have to meet Rich Haas at 10, so that trumps your meeting. Sorry I couldn't attend. Rob

Robert N. Hawk, PE
Senior Engineering Geologist/Deputy City Engineer
City of San Diego, Engineering and Capital Projects
Field Engineering Division, MS 18
9485 Aero Drive San Diego, CA 92123
(858) 573-5011
(858) 627-3297 (Fax)
rhawk@san Diego.gov

Working Together to Engineer a Better Tomorrow

>>> Michael Handal 10/01/07 3:27 PM >>>
Hi;

I just spoke to Dave Hoffmann from Ground Force Co. Dave will meet with us tomorrow morning at the 5725 SMR to discuss construction issues. Hope to see you all there.

thanks;

Michael Handal, P.E.
Project Manager
The City Of San Diego
Engineering & Capital Projects Department
Tel #: (619)533-3768
Fax #: (619)533-3071
E-mail: MHandal @Sandiego.gov

From: Jamal Batta
To: RHaas@sandiego.gov,DJarrell@sandiego.gov,AOskoui@sandiego.gov
Date: 10/1/2007 8:55:14 PM
Subject: Soledad Mtn Rd

FYI:

1. The fire hydrant leak was fixed this afternoon before 4:00 p.m.
2. I and Rob visited the impacted houses along Soledad Mtn Rd and the alley, about 20 houses. We had our 1 on 1 with each owner. The meetings went very well.

Thanks, jamal

Respectfully,

Jamal Batta, PE, CFM
Senior Civil Engineer
Engineering and Capital Projects
City of San Diego
Phone: 619 533-3769
Fax: 619 533-3071
MS # 612
JBATTA@SANDIEGO.GOV

CC: RHawk@sandiego.gov

From: Rob Hawk
To: Ventimiglia_Tim@emc.com, JBatta@sandiego.gov
Date: October 01, 2007 9:23:08 PM
Subject: Re: Soledad Mountain Road Landslide

Tim: I will be happy to meet with you this week. However, as we discussed briefly today, your property is out of the area of our immediate concern near Mr. Crabbe's home. I met with your neighbor Joeseph Tsai at 2701 Palomino Circle late last week. His house is next to you on the corner. I couldn't find anything on Mr. Tsai's property that was inconsistent with the age and construction of the subdivision. He noted some of the same issues, and we suggested that he contact a plumber.

Have you had your plumbing checked by a licensed professional? We don't inspect sewer or water on private property, so that would be a good first step. We don't believe we have major leaks on our lines in the area; most of the time when there are leaks we notice them right away. I have not observed any water in the street near your home, nor distress to the pavement or sidewalk that appeared to be connected with large scale earth movement. Regardless, please leave me a contact telephone number and I will be happy to meet with you to discuss potential problems to your home.

Rob Hawk

Robert N. Hawk, PE
Senior Engineering Geologist/Deputy City Engineer
City of San Diego, Engineering and Capital Projects
Field Engineering Division, MS 18
9485 Aero Drive San Diego, CA 92123
(858) 573-5011
(858) 627-3297 (Fax)
rhawk@sandiego.gov

Working Together to Engineer a Better Tomorrow

>>> <Ventimiglia_Tim@emc.com> 10/01/07 1:10 PM >>>

Robert and Jamal,

My name is Tim Ventimiglia. My wife, Chere, and I live at 5785 Soledad Mountain Road. I am emailing you due to the tremendous concern I have for the issues that are occurring on my street.

My neighbor at 5703 Soledad Mountain Road, Mr. Tom Crabbe, has filled me in on the details of the water leaks, possible sewer leak(s), and landslide that is occurring down our street. I've talked with one of the San Diego Gas & Electric employees today regarding the land movement, and he told me that the land has moved feet, not just inches! I see the damage to the street and the homes down my street, the damage to the street below us (Desert View), and I see that there are many city employees working on these issue. However, I still am very concerned for my property, and I wonder if I should be concerned for my life.

The ground around my home is saturated with water. See attached pictures. This hole that I dug is approximately 2 feet deep, and shows how saturated the clay is. Even though this water, I assume, could be caused by the leaks down our street - approximately 1/2 block down - our house is also higher in altitude. This makes me wonder if there are other leaks. I would like for you to come by our home and take a look at this and provide an assessment of this information.

Also, my wife and I have smelled a strong odor of sewer gas (wind was from the Northwest, not from the South where the city crews are working) many times within the last two weeks, and we wonder if there is a sewer leak North of where the city crews are working.

Last, I would like to be kept informed of what problems are found, and what measures are being implemented to address these problems. Hearing about these issues from my neighbor, I feel, is inadequate.

I look forward to your response, and your visit.

Tim Ventimiglia

<<CIMG1085.JPG>> <<CIMG1084.JPG>>

CC: MHandal@sandiego.gov, TCurtis@sandiego.gov

From: Jim Barrett
To: JFisher@sandiego.gov
Date: 10/2/2007 7:03:27 PM
Subject: Fwd: Soledad Mtn Rd Update

Jim - FYI... not sure what Jamal's reference about a fire hydrant being fixed before 4pm is all about but please take the opportunity to stress (again) to our repair crews that we need to secure all/any leaks on Soledad as quickly as possible. Thanks, jim

Jim Barrett, P.E.
Director, Water Department
City of San Diego
600 "B" Street, Suite 1300, MS 913
San Diego, CA 92101-4588
O: 619.533.7555
F: 619.533.7593
jbarrett@sandiego.gov

CC: RHaas@sandiego.gov, RuizA@sandiego.gov, SMedina@sandiego.gov

Bill Harris - Fwd: Soledad Mtn Rd Update

From: David Jarrell
To: Bill Harris; Fred Sainz; Greg Bych; Jay Goldstone; Kris Michell; Phil Rath; Ray Palmucci; Thomas Zeleny
Date: 10/2/2007 7:49 AM
Subject: Fwd: Soledad Mtn Rd Update
CC: Afshin Oskoui; Christopher Toth; Jamal Batta; Jim Barrett; Richard Haas; Rob Hawk

The below email is forwarded for your information. As discussed, the homeowner meetings will be documented. The letters to the homeowners will be prepared for distribution today. Additionally, a meeting with the entire group will be scheduled next week to provide an update on the City's plans, timelines and progress-to-date.

Please let me know if you have any questions or concerns.

Thanks,
Dave

>>> Jamal Batta 10/1/2007 8:55 PM >>>
FYI:

1. The fire hydrant leak was fixed this afternoon before 4:00 p.m.
2. Rob and I visited the impacted houses along Soledad Mtn Rd and the alley, about 20 houses. We had our 1 on 1 with each owner. The meetings went very well.

Thanks, jamal

Respectfully,

Jamal Batta, PE, CFM
Senior Civil Engineer
Engineering and Capital Projects
City of San Diego
Phone: 619 533-3769
Fax: 619 533-3071
MS # 612
JBATTA@SANDIEGO.GOV

From: David Jarrell
To: Bill Harris; Fred Sainz; Greg Bych; Jay Goldstone; Kris Michell; Phil Rath; Ray Palmucci; Thomas Zeleny
Date: Tue, Oct 2, 2007 7:50 AM
Subject: Fwd: Soledad Mtn Rd Update

The below email is forwarded for your information. As discussed, the homeowner meetings will be documented. The letters to the homeowners will be prepared for distribution today. Additionally, a meeting with the entire group will be scheduled next week to provide an update on the City's plans, timelines and progress-to-date.

Please let me know if you have any questions or concerns.

Thanks,
Dave

>>> Jamal Batta 10/1/2007 8:55 PM >>>
FYI:

1. The fire hydrant leak was fixed this afternoon before 4:00 p.m.
2. Rob and I visited the impacted houses along Soledad Mtn Rd and the alley, about 20 houses. We had our 1 on 1 with each owner. The meetings went very well.

Thanks, jamal

Respectfully,

Jamal Batta, PE, CFM
Senior Civil Engineer
Engineering and Capital Projects
City of San Diego
Phone: 619 533-3769
Fax: 619 533-3071
MS # 612
JBATTA@SANDIEGO.GOV

CC: Afshin Oskoui; Christopher Toth; Jamal Batta; Jim Barrett; Richard Haas; Rob Hawk

From: Rob Hawk
To: Cecil, Cindy
Date: Tue, Oct 2, 2007 9:23 AM
Subject: RE: 5695-5725 Soledad Mountain Road

Cindy: we have had significantly more movement on Soledad Mountain. Could you have your staff evaluate the overhead again? several residences have had concerns.

CC: Batta, Jamal; Handal, Michael; Harris, Samuel J.; Reistetter, Dave P.

From: "Afshin Oskoui" <AOskoui@SanDiego.gov>
To: <RHaas@sandiego.gov>, <RHawk@sandiego.gov>, <AOskoui@sandiego.gov>, <JBatta@sandiego.gov>, <DJarrell@sandiego.gov>
Date: Tue, Oct 2, 2007 10:29 AM
Subject: RE: Please review 'SoledadMtLetter2'

I am out at the site w/ the consultant &nd we need to include language about cutting irrigation. He needs to go back to the office to look at some seismic maps and will forward the language and limits to rob for inclusion in the letter.

-----Original Message-----

From: "Richard Haas" RHaas@sandiego.gov
To: RHawk@sandiego.gov; AOskoui@sandiego.gov; JBatta@sandiego.gov; DJarrell@sandiego.gov
Sent: 10/2/07 9:49 AM
Subject: Re: Please review 'SoledadMtLetter2'

We need a time line?

>>> David Jarrell 10/2/2007 9:23 AM >>>

My suggested revisions and comments (in track changes) are in the attached document. Pls let me know if you have any questions.

Thanks for quickly getting this together.
Dave

>>> Rob Hawk 10/2/2007 8:45 AM >>>

Please review the attached document. Please , I'll send it out to the whole group for their comments and get it out today. Rob

[Message delivered by NotifyLink]

Stan Medina - Fwd: Soladad Mtn. Road Geotechnical INvestigation/outside consultants

From: Jim Fisher
To: Stan Medina
Date: 10/2/2007 2:18:52 PM
Subject: Fwd: Soladad Mtn. Road Geotechnical INvestigation/outside consultants

FYI

>>> Rob Hawk 10/2/2007 9:30:16 AM >>>

I recieved a call from Robert Day, of American Geotechnical who is reportedly working for the homeowner at 5725 Soledad Mountain Road. He has advised me that he is recommending to his client that the house not be occupied, and that the City "Red Tag" the building. I asked him to send me an email with his reccomendations, but that his client should take his advice. With respect to the City Red Tag (No entry allowed) procedure, we will eevaluate that during a site visit. Mr. Day is a competant geotechnical engineer with whom I have worked on several litigations and a few development projects.

He also requested permission to discuss the conditions with our consultants. I replied that all geotechnical data would be available once the data has been reviewed and recieved, but direct communication & speculation by, & with our consultants was not authorized, but I would be happy to send his written request forward.

Please advise. My thought at this point is to forward requests to Tom Zelany and Afshin.

Rob Hawk

Robert N. Hawk, PE
Senior Engineering Geologist/Deputy City Engineer
City of San Diego, Engineering and Capital Projects
Field Engineering Division, MS 18
9485 Aero Drive San Diego, CA 92123
(858) 573-5011
(858) 627-3297 (Fax)
rhawk@sandiego.gov


Working Together to Engineer a Better Tomorrow

From: Rob Hawk
To: Soledad Mountain Road Group; Zeleny, Thomas
Date: 10/2/2007 9:51:29 AM
Subject: soledad Mtn overview


Attached is the .pdf of the power point for the color photos. I sent the .pdf to preserve the date of creation & integrity of the work product.

Rob Hawk


Soledad Mountain Road



Soledad Mountain Road




Soledad Mountain Road




STUDIES ON THE GEOLOGY
AND GEOLOGIC HAZARDS
OF THE GREATER SAN DIEGO AREA
CALIFORNIA


Soledad Mountain Road



Soledad Mountain Road



Soledad Mountain Road




Soledad Mountain Road



Soledad Mountain Road





5725 Soledad Mountain Road

